



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: September 25, 2006

Supervisor DDH

Mine Name: Michaud 1-4 Claims
Operator Name: Patrick Michaud
43663 Acacia Drive
Palm Desert, California 92260

Permit number: S/053/075
Date: September 12, 2006
Time: 3:45 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Inactive

Weather: Clear, hot

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated	Comment	Enforcement
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspect the site to check to see if there has been any recent activity.

Directions to Site:

See previous inspection report.

Inspection Summary:

The disturbance remains the same as it appeared during my February 28, 2006 inspection tour. A picture of the site was taken during my visit and included with this report.

Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature

Doug Jensen

Date:

9/25/06

dj:pb

cc: Patrick Michaud
Russ Schreiner, BLM, St George FO

O:\M053-Washington\S0530075-Michaud1-4\inspections\09122006insp.doc

